








Etching







charging




undercutting



sidewall residue



trenching



mask erosion